

VEHICLE INSPECTION REPORT

OV23AEN

Mercedes-Benz Sprinter 315 Progressive

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 13/03/2023

Year 2023

Mileage 21,214 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9071352N206171

Body Style Luton L3

MOT Due 12/03/2026

CAP Clean £24,200.00

CAP Average £22,800.00

CAP Below £20,000.00

Gearbox MANUAL

Tail Lift Column

WARNING LIGHT ON DASH AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		