COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR23WZH

Maxus Deliver 3 90kW 50.2kWh

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	55904
Cap Code	MXD300SW92VE A2 L

Details

Location	Bedford	**GVW**	2525kg	**CAP Clean**	£4,825.00
Reg. date	26/05/2023	**Colour**	WHITE	**CAP Average**	£4,475.00
Year	2023	**VIN**	LSH14C4C5NA139590	**CAP Below**	£3,850.00
Mileage	54,733 Miles Not Warranted	**Body Style**	Fridge Van L1	**Gearbox**	AUTOMATIC
		MOT Due	27/05/2027	**Gears**	1
Fuel Type	Electric				

WARNING LIGHT ON DASH SIDE LOADING DOOR, THERMOKING B-100 UNIT, STANDY PLUG

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

Photos











SAIC MAXUS Automotive Co.,Ltd.
e4*2007/46*1535
LSH14C4C5NA139590
2525 kg
2750 kg
1- 1180 kg
2- 1460 kg







Condition Check



Damage Photos



1: Wing osf
Dented
Between 10mm + 30mm



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Cracked
UpTo 25mm



4: Bonnet
Scratched
Over 25mm Thru Paint



5: Bumper Front
Scratched
25 to 100mm Thru Paint



6: Wing nsf
Scratched
UpTo 25mm Not Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



10: Lamp nsr
Broken
Replace



11: Door osr
Dented
With Paint Damage



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK