COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

F23AFF

Scania R 410

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Doncaster	**GVW**	44000kg	**Cab Type**	TOPLINE CAB
Reg. date	25/09/2014	**Colour**	WHITE	**Gearbox**	AUTOMATIC
Year	2014	**VIN**	YS2R6X20009188775	**Axle Combi**	6x2
Mileage	1,357,495 Km Not Warranted	**Body Style**	Tractor Unit	**Steering Combi**	Mid-Lift
Fuel Type	DIESEL	**MOT Due**	31/03/2027	**Rear Suspension**	Air

TWIN FUEL TANKS, SLIDING 5TH WHEEL

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Air conditioning

Photos














14 0km/h
357496.1km
OK
2
AdBLUE GARAJ


F23 AFF
SCANIA
SCANIA




SCANIA
6*2007/46*0038
YS2R6X20009186775
(GB)
Technically permissible
Axle group
Cab type CR19T
Serial no 9186775
Approval T 072 Fh
Cab colour 1366386
Ch No 9186775
Ch colour 1346692
ADR GTW
Ch type R 410 LA6X2/2MNA
Produced in FRANCE




CONTIN









295/80R



Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips




3: Wing nsf
Scratched
Over 25mm Not Thru Paint



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



7: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



8: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



9: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



10: Door osf
Chipped
Edge Chip



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Door osf
Scratched
Over 25mm Thru Paint



13: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



14: Seat Base Cover osf
Holed
Over 3mm



15: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK