COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

AV72OTJ

Volvo FL 250

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**GVW**	14000kg	**MOT Due**	28/02/2027
Reg. date	01/12/2022	**Colour**	YELLOW	**Cab Type**	CREW CAB
Year	2022	**VIN**	YV2T0X1A1NZ143156	**Gearbox**	AUTOMATIC
Mileage	445,429 Km Warranted	**Body Style**	Recovery	**Axle Combi**	4x2
Fuel Type	DIESEL	**Service history**	None	**Rear Suspension**	Air

NO REMOTE BONIFACE STVLA+SCL DEMOUNT SLIDE BODY (YEAR 2022), C/W SPEC LIFT, SLIDING WINCH, DYNA CYCLE, 3POINT SEAT BELTS, UNDERSEAT STORAGE

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Park assist camera
- Rear electric windows
- Digital radio
- Drivers airbag

Photos










11:57 0km/h
OUT 445430.3km


Volvo Truck Corporation
e2*2007/46*0034
YU2T0X1A1N2143156
GB
14000 14000 kg
21000 21000 kg
5800 5800 kg
9440 9440 kg
96/53/EC article10
Compliant









MODEL: 6T VLA + SCL
SERIAL No.: 10-20647-22
BUILD SHEET: 20647
TEST No.: 3801
DATE: 17:10:2022
RATING TEST SWL
SECOND CAR LIFT 2000 2600 2000
CE UK CA













volvo
12:00 0 0km/h
OUT 445430.3km





Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front
Chipped
Multiple Chips



4: Door nsf
Scratched
UpTo 25mm Not Thru Paint



5: Door nsf
Chipped
1 To 5



6: Door nsr
Chipped
1 To 5



7: Door nsr
Chipped
Edge Chip



8: Door nsr
Chipped
1 To 5



9: Qtr Panel nsr
Chipped
1 To 5



10: Qtr Panel osr
Chipped
Multiple Chips



11: Qtr Panel osr
Chipped
Multiple Chips



12: Door osf
Scratched
UpTo 25mm Not Thru Paint



13: Door osf
Chipped
Multiple Chips

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Turbo Boosting	OK		
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows	OK	Radio	OK
		Steering	OK