

VEHICLE INSPECTION REPORT

YD73ZHB

Iveco S-Way 490

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Code	999900

Details

Location	Doncaster	Colour	WHITE	Gearbox	AUTOMATIC
Reg. date	01/10/2023	VIN	ZCFS62NU30C513801	Axle Combi	6x2
Year	2023	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	404,012 Km Warranted	Service history	None	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	31/08/2027		
GVW	44000kg	Cab Type	HIGH ROOF SLEEPER CAB		


SLIDING 5TH WHEEL





Tyres					
NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OSO1	OSO2	OSO3	OSO4	


Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Navigation system
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Door Moulding nsf
Scratched (Painted)
Over 25mm Thru Paint



3: Qtr Panel Moulding ns
Broken
Replace



4: Qtr Panel Moulding os
Broken
Replace



5: Door osf
Dented
With Paint Damage



6: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK