COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CK75EGV

Peugeot Partner 1.5 BLUEHDI 100PS PROFESSIONAL

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	62220
Cap Code	PEPA15PP10VDTM2 6 L

Details

Location	Bedford	**GVW**	2390kg	**CAP Clean**	£12,750.00
Reg. date	30/09/2025	**Colour**	WHITE	**CAP Average**	£12,250.00
Year	2025	**VIN**	VR3EDYHT8SJ733948	**CAP Below**	£11,100.00
Mileage	23,158 Miles Not Warranted	**Body Style**	Fridge Van SWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	29/09/2028	**Gears**	6

AD BLUE, SIDE LOADING DOOR, THERMOKING B-100 UNIT, STANDY PLUG, E/MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Rear parking sensor
- Air conditioning
- Front electric windows

Photos










transcan




MAR
COOLING
SOLUTIONS
VR3EDYHT8SJ733






THERMO KING
B-100 ECO




THERMO KING










Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Panel Front
Scratched
Over 25mm Not Thru Paint



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK