COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FN20AXT

Daf CF 410

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**GVW**	32000kg	**Cab Type**	DAY CAB
Reg. date	07/08/2020	**Colour**	GREEN	**Gearbox**	AUTOMATIC
Year	2020	**VIN**	XLRACM4100G296657	**Axle Combi**	8x2
Mileage	223,114 Km Not Warranted	**Body Style**	Refuse Collector	**Rear Suspension**	Air
Fuel Type	DIESEL	**MOT Due**	30/09/2027		

HILLEND ENGINEERING EHP21123 BODY, REAR LIFT

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim

Photos











000km/h
022315.0km
OK

R
N
D



DAF TRUCKS N.V.
Type
Motor no.


















Condition Check



Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door osf
Dented
Over 30mm



6: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK