COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FN20AXV

Daf CF 410

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**GVW**	32000kg	**Cab Type**	DAY CAB
Reg. date	07/08/2020	**Colour**	GREEN	**Gearbox**	AUTOMATIC
Year	2020	**VIN**	XLRACM4100G296926	**Axle Combi**	8x2
Mileage	250,293 Km Not Warranted	**Body Style**	Refuse Collector	**Rear Suspension**	Air
Fuel Type	DIESEL	**MOT Due**	31/08/2027		

HELLEND ENGINEERING EHP21123 BODY, REAR LIFT

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features


- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim

Photos













000km/h
0250294.0km
OK
MERCY

R
N
D


DAF TRUCKS N.V.
Type
Motor no.


FORS





FORS












Condition Check



Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



4: Door nsf
Chipped
Multiple Chips



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door osf
Scratched
Over 25mm Thru Paint



7: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK