COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PL68MGJ

Fiat DUCATO MAXI 35 2.3 MULTIJET 130PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	31377
Cap Code	FIDU233ML3DDTM2 5 L

Details

Location	Avonmouth	**Colour**	WHITE	**CAP Below**	£5,225.00
Reg. date	13/02/2019	**VIN**	ZFA25000002J28488	**Gearbox**	MANUAL
Year	2019	**Body Style**	Dropside LWB	**Gears**	6
Mileage	158,169 Miles Warranted	**MOT Due**	24/02/2027	**Tail Lift**	Column
Fuel Type	DIESEL	**CAP Clean**	£7,775.00		
GVW	3500kg	**CAP Average**	£6,700.00		

AD BLUE, TOW BAR, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features



- Bluetooth connection
- Drivers airbag
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim
- Front electric windows

Photos












1700
1520
3220
kg

HIGHWAY
MAINTENANCE




Do not walk close to
this vehicle at any time



R
1
3
5
2
4
6


FIAT
AIRBAG

24/7 RoadCrew Support
0113 457 1000
RF RD Reader





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Scratched
Over 25mm Thru Paint



3: Door Moulding nsf
Missing
Replace



4: Door nsf
Scratched
Over 25mm Thru Paint



5: B Post ns
Scratched
Over 25mm Thru Paint



6: B Post os
Scratched
Over 25mm Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint



8: Sill os
Scratched
Over 25mm Thru Paint



9: Door osf
Dented
Over 30mm



10: Door Mirror Assy osf
Broken
Replace



11: Wing osf
Scratched
Over 25mm Thru Paint



12: A Post os
Scratched
Over 25mm Thru Paint



13: Bonnet
Scratched
Rusted



14: Fascia Panel
Missing
Replace



15: Fascia Panel
Broken
Replace



16: Sunvisor os
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		