

## VEHICLE INSPECTION REPORT

**CJ23VCE**

### Citroen Relay 2.2 BlueHDi H2 Van 140ps Enterprise Edition

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Buyer To Apply

#### Details

Reg. date 31/07/2023

VIN VF7YCBPFCPG023198

CAP Below £10,100.00

Year 2023

Body Style Panel Van L3

Gearbox MANUAL

Mileage 31,304 Miles Not Warranted

MOT Due 30/07/2026

Gears 6

Fuel Type Diesel

CAP Clean £12,200.00

Colour WHITE

CAP Average £11,500.00

AD-BLUE, SIDE LOAD DOOR, E/MIRRORS

#### Tyres

NSF

NSR

OSF

OSR

Spare


## Features

- Bluetooth connection
- Cruise control
- Navigation system
- Park assist camera
- Auxiliary input socket
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

## Photos










## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Qtr Panel nsr  
Chipped  
Multiple Chips





3: Door nsf  
Chipped  
Multiple Chips



4: Qtr Panel nsr  
Chipped  
Multiple Chips



5: Qtr Panel nsr  
Dented  
With Paint Damage



6: Qtr Panel nsr  
Dented  
With Paint Damage



7: Door osr  
Dented  
Over 30mm



8: Door osr  
Dented  
Over 30mm



9: Door Mirror Assy osf  
Scuffed (Unpainted)  
UpTo 100mm



10: Seat Base Cover osf  
Soiled  
Heavy

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			