

VEHICLE INSPECTION REPORT

DV73PXD

Vauxhall Vivaro 3100 2.0d 145PS H1 Prime

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 27/09/2023

Year 2023

Mileage 20,467 Miles Not Warranted

Fuel Type Diesel

Colour GREY

VIN VXEVFEHTMP7856849

Body Style Panel Van L2

MOT Due 26/09/2026

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH AD-BLUE, TWIN SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR



Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Scratched
Over 25mm Not Thru Paint



3: Door nsf
Scratched
Over 25mm Not Thru Paint



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint



8: Door osf
Dented
Over 30mm



9: Seat Base Cover osf
Soiled
Heavy



10: Seat Base Cover nsf
Soiled
Heavy



11: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		