

VEHICLE INSPECTION REPORT

DV73P XK

Vauxhall Vivaro 3100 2.0D 145PS PRIME

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 27/09/2023

Year 2023

Mileage 28,673 Miles Not Warranted

Fuel Type Diesel

Colour GREY

VIN VXEVFEHTMP7855747

Body Style Panel Van L2

MOT Due 26/09/2026

CAP Clean £13,600.00

CAP Average £12,850.00

CAP Below £11,300.00

Gearbox MANUAL

Gears 6

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Auxiliary input socket
- Metallic Paint
- Cloth seat trim
- Cruise control
- Digital radio
- Drivers airbag
- Park assist camera
- Air conditioning
- Passenger airbag
- Rear parking sensor
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Wheel nsf
Dented
Over 30mm (Steel)



3: Qtr Panel osr
Scratched
Over 25mm Thru Paint



4: Door osf
Scratched
Over 25mm Thru Paint



5: Door osf
Scratched
Over 25mm Thru Paint



6: Door osf
Scratched
Over 25mm Not Thru Paint



7: Seat Base Cover osf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		