COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MF73ENH

Iveco Daily 35-140

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	46823
Cap Code	IVDA235S44BDTM2 5 L

Details

Location	Doncaster	**Colour**	WHITE	**CAP Below**	£10,300.00
Reg. date	08/09/2023	**VIN**	ZCFCL35A70D739956	**Gearbox**	MANUAL
Year	2023	**Body Style**	Dropside LWB	**Gears**	6
Mileage	64,638 Miles Not Warranted	**MOT Due**	07/09/2027	**Tail Lift**	Column
Fuel Type	DIESEL	**CAP Clean**	£12,850.00		
GVW	3500kg	**CAP Average**	£11,950.00		

AD-BLUE, E/ MIRRORS, 3750 WB

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Navigation system
- Front electric windows
- Park assist camera
- Drivers airbag



Photos













0
50
100
%
AdBlue 36%
64639 mi
Trip A
1105 mi


IVECO
IVECO SpA
e3*2007/46*0118*
ZCFCL35A70D739956
3500 kg
7000 kg
1 - 1907 kg
2 - 2240 kg
Type IS35S12AA
Wheelbase 3750
N° of axles 2
Engine Type F1AGL4118
Engine power kW 100
Made in SPAIN
0.502


3500KG






MF73 ENH








Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Wing nsf
Scratched
Over 25mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



4: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



5: Door Mirror Assy osf
Broken
Replace



6: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK