COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**CK75EOE**

## Peugeot Partner 1.5 BLUEHDI 100PS PROFESSIONAL

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Plus VAT |
| **V5** | Buyer To Apply |
| **Cap Id** | 62220 |
| **Cap Code** | PEPA15PP10VDTM2 6 L |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Location** | Bedford | **GVW** | 2390kg | **CAP Clean** | £13,250.00 |
| **Reg. date** | 30/09/2025 | **Colour** | WHITE | **CAP Average** | £12,700.00 |
| **Year** | 2025 | **VIN** | VR3EDYHT7SJ741491 | **CAP Below** | £11,500.00 |
| **Mileage** | 17,490 Miles Not Warranted | **Body Style** | Fridge Van SWB | **Gearbox** | MANUAL |
| **Fuel Type** | DIESEL | **MOT Due** | 29/09/2028 | **Gears** | 6 |

*WARNING LIGHTS ON DASH* AD BLUE, E/MIRRORS, HEATED WINDSCREEN, THERMOKING B-100 UNIT, STANDY PLUG

### Tyres

| | |
|---|---|
| **NSF** | |
| **NSR** | |
| **OSF** | |
| **OSR** | |
| **Spare** | |

## Features

- Rear parking sensor
- Air conditioning
- Front electric windows

## Photos
















STELLANTIS AUTO SAS
VR3EDYHT7SJ741491
2390 KG
3390 KG
1 – 1200 KG
2 – 1400 KG





THERMO KING
B-100

THERMO KING
B-100






# Condition Check




## Damage Photos




1: Bonnet
Chipped
1 To 5



2: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



3: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



5: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

## Interior

| | | | |
|---|---|---|---|
| **Carpet Condition** | OK | **Upholstery Condition** | OK |
| **Seat Condition** | OK | **Odour** | No |

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | Fault |