COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BG19ABO

Iveco Daily 50-150

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**Colour**	WHITE	**MOT Due**	30/04/2027
Reg. date	05/03/2019	**VIN**	ZCFC150B405218978	**Cab Type**	DAY CAB
Year	2019	**Body Style**	Access Platform	**Gearbox**	MANUAL
Mileage	99,853 Km Warranted	**Service history**	Yes	**Axle Combi**	4x2
Fuel Type	DIESEL	**Last service date**	27/03/2026	**Rear Suspension**	Steel
GVW	5200kg	**Last service miles**	55,347		

KLUBB K42PL PLATFORM

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**


Features


- Park assist camera

Photos










IVECO
OK
VANWEIGH




CPL
STOP





Plaque
Constructeur
CE
K42P
K4218089
12/2018
3.4
kW
200
kg
400
N
12.5
m/s


80dB
WARNING






CUMBERLAND PLATFORMS UK
STAGE 2
ZCFC150B405218978
IVECO SPA
kg
kg










Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Cracked
Replace



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door osr
Dented
Over 30mm



6: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



7: Carpets Front
Holed
Over 3mm



8: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK