COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE65UZH

Daf LF 220

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster
Reg. date	16/10/2015
Year	2015
Mileage	918,037 Km Warranted
Fuel Type	DIESEL
GVW	18000kg
Colour	RED

VIN	XLRAEL3700L448285
Body Style	Box Van
Service history	Yes
Service documents	Printout
Last service date	16/05/2025
Last service miles	786,518
MOT Due	31/07/2027

Cab Type	DAY CAB
Gearbox	AUTOMATIC
Axle Combi	4x2
Rear Suspension	Steel
Rear Doors	Roller
Tail Lift	Cantilever

WARNING LIGHTS ON DASH

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features


- Cruise control
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning
- Front electric windows

Photos








14:43 g 0km/h
918037.7km



Plate
REPLACEMENT



DAF TRUCKS N.V.
DAF






PE65 UZH





Condition Check



Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



3: Tailgate
Rusted
Holed



4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Door osf
Dented
With Paint Damage



6: Door osf
Scratched
Over 25mm Thru Paint



7: Wing osf
Scratched
Over 25mm Thru Paint




8: Screen Front
Chipped
Over 10mm



9: Door Pad osf
Soiled
Heavy



10: Seat Base Cover nsf
Holed
Over 3mm



11: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	**Upholstery Condition**	Poor
Seat Condition	Poor	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK