COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MT23OKH

Ford Ranger WILDTRAK 2.0 ECOBLUE 213PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	44067
Cap Code	FORA20WILD7DTA4 6 L

Details

Location	Bedford	**Colour**	WHITE	**CAP Below**	£10,900.00
Reg. date	25/04/2023	**VIN**	6FPPXXMJ2PNR76488	**Gearbox**	AUTOMATIC
Year	2023	**Body Style**	Pickup Double Cab	**Gears**	1
Mileage	78,559 Miles Not Warranted	**MOT Due**	24/04/2027	**Axle Combi**	4x4
Fuel Type	DIESEL	**CAP Clean**	£13,700.00		
GVW	3270kg	**CAP Average**	£12,700.00		

AD BLUE, E/MIRRORS, TOW BAR, ALLOY WHEELS

Tyres



NSF	
NSR	
OSF	
OSR	
Spare	

Features



- Front parking sensor
- Air conditioning
- Navigation system
- Front electric windows
- Park assist camera
- Rear parking sensor


Photos













FORD
e5*2007/46*0080
6FPPXXMJ2PNR76488
3270 KG
6260 KG
1480 KG
1910 KG
VIN
2AB
0.50
MADE IN SOUTH AFRICA







Phone
No phone connected,
please see the
touchscreen
P R N D S






Condition Check



Damage Photos




1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Bumper Rear
Scratched
25 to 100mm Thru Paint



4: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK