COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BD73UEC

Ford Ranger WILDTRAK 2.0 ECOBLUE 205PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	56276
Cap Code	FORA20WILD7DTA4 7 L

Details

Location	Bedford	**Colour**	WHITE	**CAP Below**	£17,450.00
Reg. date	30/11/2023	**VIN**	6FPPXXMJ2PPT83944	**Gearbox**	AUTOMATIC
Year	2023	**Body Style**	Pickup Double Cab	**Gears**	1
Mileage	43,388 Miles Not Warranted	**MOT Due**	29/11/2026	**Axle Combi**	4x4
Fuel Type	DIESEL	**CAP Clean**	£21,900.00		
GVW	3280kg	**CAP Average**	£20,250.00		

WARNING LIGHTS ON DASH, BRAKES NEED ATTN AD BLUE, E/MIRRORS, TOW BAR, HEATED SEATS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front parking sensor
- Air conditioning
- Navigation system
- Front electric windows
- Park assist camera
- Rear electric windows
- Rear parking sensor
- Leather seat trim

Photos














FORD
e5*2007/46*0080
6FPPXXMJ2PPT83944
3280 kg
6500 kg
1490 kg
1959 kg
2AB
0.50
VIN
MADE IN SOUTH AFRICA






TERRITORY








Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
Over 10mm



3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



4: Qtr Panel nsr
Cracked
Replace



5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel osr
Scratched
UpTo 25mm Not Thru Paint



7: Door osf
Scratched
UpTo 25mm Not Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	Fault	Service indicator light illuminated	OK