COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**HG25GZR**

## FORD / ROLLER TEAM ZEFIRO 675 2.0 ECOBLUE

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Plus VAT |
| **V5** | Buyer To Apply |
| **Cap Code** | 999900 |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Location** | Avonmouth | **Fuel Type** | DIESEL | **Body Style** | Motorhome |
| **Reg. date** | 21/05/2025 | **GVW** | 3500kg | **MOT Due** | 20/05/2028 |
| **Year** | 2025 | **Colour** | WHITE/SILVER | **Gearbox** | AUTOMATIC |
| **Mileage** | 25,146 Miles Not Warranted | **VIN** | WF0DXXTTRDRT27291 | | |

*WARNING LIGHTS ON DASH* 6 BERTH, AD BLUE, ALLOY WHEELS, E/MIRRORS, HEATED WINDSCREEN, 5 SEATS WITH 3PT. SEATBELTS, OVERHEAD DOUBLE BED, DOUBLE BED, SINGLE BED, TOILET, SHOWER, OVEN, 3 RING GAS HOB, SINK, FRIDGE, FREEZER, STORAGE

### Tyres

| | |
|---|---|
| **NSF** | |
| **NSR** | |
| **OSF** | |
| **OSR** | |
| **Spare** | |


## Features


- Front parking sensor
- USB/iPod interface
- Drivers airbag
- Navigation system
- Manual sunroof
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Digital radio
- Front electric windows
- Cloth seat trim


## Photos










R
N
P
D
M

ROLLER TEAM
UK
HG25 GZR

Ford
AIRBAG

FORD
BLFB
0.50
"WF0DXXTTRDRT27291"
W(mm)
D 3750
L(mm)
a(mm)
FDD









1 X
15 Kg

675






















POW-Keeper1220
MPPT
SET
SOLAR
CHARGE CONTROLLER

VISION PLUS


12:20 11.11.26
Temperature
Resources
1 Notification
Unlock Screen








RCCB
MCB1
MCB2


RCCB
MCB1
MCB2














ROLLER TEAM
TRIGANO SPA
e13*2007/46*1858*
Fase 2
*ZAJTFDD0000152479
3500 Kg
5500 Kg
2000 Kg
2250 Kg
TFDD G2FDR AAGG205
WF0





# Condition Check




## Damage Photos




1: Bonnet
Chipped
Multiple Chips




2: Door Mirror Assy nsf
Broken
Replace



3: Bumper Rear
Cracked
Over 25mm



4: Fascia Trim
Missing
Replace



5: Fascia Trim
Missing
Replace

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | - |

| | | | |
|---|---|---|---|
| Engine Runs | OK | No Excessive Smoking | OK |
| Brakes | OK | | |
| Parking Brake | OK | | |
| EML light illuminated | OK | Oil warning light illuminated | Fault |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | Fault |