COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HG25UYY

FORD / ROLLER TEAM AUTO ROLLER 746 2.0 ECOBLUE

Inspection

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Avonmouth	**Fuel Type**	DIESEL	**Body Style**	Motorhome
Reg. date	21/07/2025	**GVW**	3500kg	**MOT Due**	20/07/2028
Year	2025	**Colour**	WHITE/SILVER	**Gearbox**	AUTOMATIC
Mileage	13,754 Miles Not Warranted	**VIN**	WF0DXXTTRDRK43424		

6 BERTH, AD BLUE, ALLOY WHEELS, E/MIRRORS, HEATED WINDSCREEN, 6 SEATS WITH 3PT. SEATBELTS, OVERHEAD DOUBLE BED, DOUBLE BED, TOILET, SHOWER, OVEN, 3 RING GAS HOB, SINK, FRIDGE FREEZER, REAR STORAGE

Tyres

NSF
NSR
OSF
OSR
Spare

Features


- Bluetooth connection
- Park assist camera
- Air conditioning
- Central locking
- Cruise control
- Digital radio
- Front electric windows
- Cloth seat trim
- Front parking sensor
- USB/iPod interface
- Drivers airbag
- Navigation system
- Manual sunroof
- Passenger airbag


Photos












Please check surroundings for safety.

ROLLER TEAM
UK
HG25 UYY

Ford
AIRBAG


TRANSIT
CAMPER
2.0 l HPCR Panther Diesel
165 PS
Stage 6 HD
410EF
BLHB
FORD
e1*2007/46*1098
WF0DXXTTRDRK43424
4100
5750
2000
2500
W(mm)
D 3954
L(mm)
a(mm)
FDD





Off





30 mbar


20 Kg






ROLLER TEAM
TRIGANO S.A.
e13*2007/46*1858*
Fase 2
*ZAJTFDD0000152960
3500 Kg
5500 Kg
2000 Kg
2500 Kg
TFDD J2HDR AART205
WF0DXXTTRDRK43424












12V
SAT
TV
100W


















MPPT
SOLAR
CHARGE CONTROLLER


















Resources
Batteries
Starter battery
13.6 V
Leisure battery
14.0 V
Water
Refill
66 %
0 %
ROLLER TEAM





R
N
P
D
M






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: D Post os
Scratched
Over 25mm Thru Paint




3: Door osf
Scratched
Over 25mm Thru Paint



4: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint



5: Door osf
Dented
Over 2 UpTo 10mm



6: Qtr Panel Trim ns
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		