COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HJ25SFU

FORD / ROLLER TEAM ZEFIRO 665 2.0 ECOBLUE

Inspection

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Avonmouth	**Fuel Type**	DIESEL	**Body Style**	Motorhome
Reg. date	03/04/2025	**GVW**	3500kg	**MOT Due**	02/04/2028
Year	2025	**Colour**	WHITE	**Gearbox**	MANUAL
Mileage	21,955 Miles Not Warranted	**VIN**	WF0DXXTTRDRL80901		

AD BLUE, E/MIRRORS, 4 SEATS WITH 3PT. SEATBELTS, OVERHEAD DOUBLE BED, TOILET, SHOWER, 3 RING GAS HOB, OVEN, SINK STORAGE, FRIDGE, REAR STORAGE, BIKE RACK

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	


Features

- Bluetooth connection
- Digital radio
- Front electric windows
- Cloth seat trim
- Cruise control
- USB/iPod interface
- Drivers airbag
- Front parking sensor
- Manual sunroof
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking

Photos





Ford
AIRBAG


ROLLER TEAM
HJ25 SFU

R 1 3 5
2 4 6

FORD
BKFB
0.50
"WF0DXXTTRDRL80901"
3550 kg
5700 kg
2000 kg
2150 kg
W(mm)
L(mm)
a(mm)
L 3300
FDD





Off



15 Kg.









16:51 11.11.26
Resources
Room climate
Hot water
Switches
Timers
Notifications















RCCB
MCB1
MCB2

MPPT
SOLAR




ROLLER TEAM
TRIGANO S.p.A.
e13*2007/46*1858*
Fase 2
*ZAJTFDD00J0150090
350(Kg
550J Kg
200 Kg
215 0 Kg
TFDD G2EDR 8MGM204
WF0DXXTTRDRL80901

Please check surroundings for safety.
A/C
MAX
AUTO
22.5°






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Scratched
UpTo 25mm Thru Paint




3: Qtr Panel Moulding ns
Broken
Replace



4: Reflector nsr
Broken
Replace



5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



8: Door osf
Scratched
Over 25mm Thru Paint



9: Door osf
Scratched
Over 25mm Not Thru Paint



10: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		