COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HJ23VYD

FORD / ROLLER TEAM AUTO ROLLER 746 2.0 ECOBLUE

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Avonmouth	**Fuel Type**	DIESEL	**Body Style**	Motorhome
Reg. date	01/07/2023	**GVW**	3500kg	**MOT Due**	02/08/2027
Year	2023	**Colour**	SILVER/WHITE	**Gearbox**	AUTOMATIC
Mileage	33,244 Miles Not Warranted	**VIN**	WF0DXXTTRDPE37181		

OUTSTANDING RECALL, 6 BERTH, AD BLUE, ALLOY WHEELS, E/MIRRORS, HEATED WINDSCREEN, 5 SEATS WITH 3PT. SEATBELTS, OVERHEAD DOUBLE BED, DOUBLE BED, TOILET, SHOWER, OVEN, GAS HOB, SINK, FRIDGE, REAR STORAGE, BIKE RACK

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- USB/iPod interface
- Drivers airbag
- Cruise control
- Manual sunroof
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Digital radio
- Front electric windows
- Cloth seat trim


Photos














Ford
AIRBAG


ROLLER TEAM
HJ23 VYD

P
R
N
D
M

TRANSIT
CAMPER
2.0 l HPCR Panther Diesel
155 PS
Stage 6 HD
350EF
N0HA
FORD
e1*2007/46*1098
* WF0DXXTTRDPE37181 *
3550 kg
4250 kg
1850 kg
2250 kg
W(mm)
C 3954
L(mm)
FDD







HJ23 VYD


1 X
15 Kg














12V
SAT
TV
180W


13:13 11.11.26
Temperature
Resources
12°
9°
1 Notification
Unlock Screen
ROLLER TEAM





THETFORD







VISION PLUS
Digital TV Amplifier VP2

VISION PLUS
Digital TV Amplifier VP2
12-24VDC
TV2
TV1
ANT IN

PWM Solar Charge Controller
Vechline
SETUP
























ROLLER TEAM
TRIGANO SPA
e13*2007/46*1858*
Fase 2
*ZAJTFDD0000132233
3500 Kg
4250 Kg
1850 Kg
2250 Kg
TFDD CH1 A254DA
V/F0DXXTTRDPE37181





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Scratched
UpTo 25mm Thru Paint



3: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Door osf
Dented
Over 2 UpTo 10mm



6: Door osf
Scratched
Over 25mm Thru Paint



7: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint



8: Bumper Front
Scratched
UpTo 25mm Thru Paint



9: Bonnet
Scratched
UpTo 25mm Thru Paint



10: Seat Base Cover osr
Torn
Over 3mm



11: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		