COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HG23NJN

FORD / ROLLER TEAM ZEFIRO 685 2.0 ECOBLUE

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Avonmouth	**Fuel Type**	DIESEL	**Body Style**	Motorhome
Reg. date	24/05/2023	**GVW**	3500kg	**MOT Due**	10/06/2027
Year	2023	**Colour**	WHITE	**Gearbox**	MANUAL
Mileage	36,731 Miles Not Warranted	**VIN**	WF0DXXTTRDPD11692		

OUTSTANDING RECALL 4 BERTH, AD BLUE, E/MIRRORS, 3 SEATS WITH 3PT. SEAT BELTS, OVERHEAD BED, DOUBLE BED, TOILET, SHOWER, OVEN, GAS HOB, SINK, FRIDGE, FREEZER, REAR STORAGE, BIKE RACK

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Bluetooth connection
- USB/iPod interface
- Drivers airbag
- Cruise control
- Manual sunroof
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Digital radio
- Front electric windows
- Cloth seat trim


Photos










ROLLER TEAM
HG23 NJN
UK


TRANSIT
CAMPER
2.0 l HPCR Panther Diesel
130 PS
Stage 6.2
350EF
BKFB
0.50
FORD
e1*2007/46*1098
WF0DXXTTRDPD11692
3550
5065
1850
2250
kg
W(mm)
L(mm)
H(mm)
J
3954
FDD













ROLLER TEAM
TRIGANO SPA
e13*2007/46*1858*
Fase 2
*ZAJTFDD0000131523
3500 Kg
5065 Kg
1850 Kg
2250 Kg
TFDD CED M255KB
WF0DXXTTRDPD11692























11.11.26
Temperature
Resources
15°
9°
Unlock Screen


VISION PLUS
Digital TV Amplifier VP2
12-24vDC
TV2
TV1
ANT IN

PWM Solar Charge Controller
Vechline





















12V
SAT
TV
120W


MCCB
MCB1
MCB2

R 1 3 5
2 4 6






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Scratched
UpTo 25mm Thru Paint



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Qtr Panel Moulding ns
Broken
Replace



5: Bumper Rear
Scratched
Over 100mm Thru Paint



6: Qtr Panel nsr
Dented
With Paint Damage



7: Bumper Rear
Scratched
Up To 25mm Thru Paint



8: Bumper Rear
Cracked
Over 25mm



9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		