COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BN24HYT

Ford Transit 350 2.0 ECOBLUE 130PS LEADER

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	44615
Cap Code	FOTR20L3L3HDTM2 5 L

Details

Location	Doncaster	**GVW**	3500kg	**CAP Average**	£13,250.00
Reg. date	30/04/2024	**Colour**	WHITE	**CAP Below**	£11,650.00
Year	2024	**VIN**	WF0EXXTTRERB64322	**Gearbox**	MANUAL
Mileage	50,141 Miles Not Warranted	**Body Style**	Panel Van L4	**Gears**	6
Fuel Type	DIESEL	**CAP Clean**	£14,050.00		

AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Front electric windows
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Central locking
- Digital radio
- Cloth seat trim

Photos










FORD
e1*2007/46*1100
* WF0EXXTTRERB64322 *
TRANSIT
BASE
BKRA
0.50
3500
5550
1750
2250
B 3750
FCD

R 1 3 5
2 4 6

Dist to empty 5°
Driver door open
50141.2 mls
120
MPH
















Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Not Thru Paint



2: Bonnet
Dented
With Paint Damage



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

No Image

5: Door nsf
Dented
With Paint Damage



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



9: Door osr
Scratched
Over 25mm Thru Paint



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



12: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



13: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK