COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HT23VXF

Ford Transit 350 2.0 EcoBlue 130ps LEADER

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	45238
Cap Code	FOTR2035331DTM2 5 L

Details

Location	Livingston	**GVW**	3500kg	**CAP Clean**	£18,150.00
Reg. date	27/07/2023	**Colour**	WHITE	**CAP Average**	£16,800.00
Year	2023	**VIN**	WF0CXXTTRCPK66404	**CAP Below**	£14,450.00
Mileage	42,431 Miles Not Warranted	**Body Style**	Tipper Double Cab	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	29/07/2027	**Gears**	6

ALUMINIUM TIPPER BODY, TOW BAR, AD-BLUE.

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features


- Radio/CD
- Front electric windows
- Central locking

Photos









HIGHWAY MAINTENANCE
HT23 VXF

UK
NI
TRANSIT
BASE
2.0 I-HPCR Panther Diesel
130 PS Stage IV 2
350L
BKRA
0.50
FORD
e1*2007/46*1096
WF0CXXTTRCPK66404
3500 kg
6500 kg
1850 kg
2450 kg
W(mm)
H 3954
L(mm)
a(mm)







HIGHWAY MAINTENANCE
HT23 VXF






Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Wing osf
Dented
With Paint Damage



3: Door osf
Dented
With Paint Damage



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK