COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR23XCG

Maxus Deliver 9 D20 2.0 150PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	MXD920L150HDTM2 L

Details

Location	Doncaster	**GVW**	3500kg	**MOT Due**	07/07/2027
Reg. date	28/06/2023	**Colour**	WHITE	**Gearbox**	MANUAL
Year	2023	**VIN**	LSH14J7C3PA087024	**Gears**	6
Mileage	67,231 Miles Not Warranted	**Body Style**	Fridge Van LWB		
Fuel Type	DIESEL	**Service history**	None		

WARNING LIGHTS ON DASH THERMOKING V-200 MAX UNIT, STANDBY PLUG, AD-BLUE, E/MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking
- Front electric windows
- Cloth seat trim

Photos

















25%
Avg Speed
0 mph
67231mi




SAIC MAXUS Automotive Co.,Ltd.
64*2018/858*00074
LSH14J7C3PA087024
3500 kg
6000 kg
1- 1950 kg
2- 1900 kg







AIRBAG


















Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



3: Qtr Panel nsr
Dented
With Paint Damage



4: Door nsr
Dented
With Paint Damage



5: Door osr
Dented
With Paint Damage



6: Door osr
Dented
With Paint Damage




7: Qtr Panel Moulding os
Broken
Replace



8: Dash Warning Lights
Displayed
No Action



9: Seat Base Cover osf
Soiled
Heavy



10: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK