COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HT23VYE

Ford Transit 350 2.0 ECOBLUE 130PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	45234
Cap Code	FOTR201T1RMDTM2 5 L

Details

Location	Avonmouth	**GVW**	3500kg	**CAP Clean**	£16,850.00
Reg. date	27/07/2023	**Colour**	WHITE	**CAP Average**	£15,650.00
Year	2023	**VIN**	WF0CXXTTRCPK65072	**CAP Below**	£13,450.00
Mileage	54,678 Miles Not Warranted	**Body Style**	Tipper Double Cab	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	28/07/2027	**Gears**	6

OUTSTANDING RECALL, AD BLUE, TOW BAR,

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features

- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Front electric windows
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Central locking



Photos










TRANSIT
BASE
2.0 I4PCR Panther Diesel
130 PS
Stage 6.2
350L
BKRA
0.50
FORD
e1*2007/46*1096
3500
6500
1850
2450
H 3954
FED



Intruder
Lower
Ignition switch
ON



WF0CXXTTRCPK65072
STAGE 2
e11*2007/46*1563*08
VFS (Southampton) Ltd
8 Barton Park Ind Est.
Eastleigh, Hants,
SO50 6RR


R 1 3 5
2 4 6

Ford












Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Over 5mm



3: Wing nsf
Scratched
Over 25mm Not Thru Paint



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Door nsf
Chipped
Over 5mm



7: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



8: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: D Post ns
Scratched
Over 25mm Not Thru Paint



11: D Post os
Scratched
Over 25mm Not Thru Paint



12: Door osr
Chipped
Over 5mm



13: Door osr
Scratched
Over 25mm Not Thru Paint



14: Door osf
Scratched
Over 25mm Not Thru Paint



15: Door osf
Chipped
Over 5mm



16: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



17: Roof
Rusted
Over 5mm



18: Bumper Front
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK

Commercial Vehicle Auctions Limited