COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HT23VXN

Ford Transit 350 2.0 ECOBLUE 130PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	45234
Cap Code	FOTR201T1RMDTM2 5 L

Details

Location	Avonmouth	**GVW**	3500kg	**CAP Clean**	£23,600.00
Reg. date	27/07/2023	**Colour**	WHITE	**CAP Average**	£21,850.00
Year	2023	**VIN**	WF0CXXTTRCPL52434	**CAP Below**	£18,800.00
Mileage	50,952 Miles Not Warranted	**Body Style**	Tipper Double Cab	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	26/07/2027	**Gears**	6

OUTSTANDING RECALL, AD BLUE, TOW BAR

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Front electric windows
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Central locking
- Digital radio
- Cloth seat trim

Photos
















TRANSIT
BASE
130 PS
350L
BKRA
0.50
FORD
e1*2007/46*1096
* WF0CXXTTRCPL52434 *
3500
6500
1850
2450
H 3954
FED

ON
Raise
Lower
Isolation switch




WF0CXXTTRCPL52434
STAGE 2
VFS (Southampton) Ltd
8 Barton Park Ind Est.
Eastleigh, Hants,
SO50 6RR

Ford
AIRBAG


R 1 3 5
2 4 6








Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Scratched
Over 25mm Not Thru Paint




3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Wing nsf
Chipped
Over 5mm



5: Wheel nsf
Corroded
Light



6: Door Mirror Assy nsf
Broken
Replace




7: A Post ns
Scratched
Over 25mm Not Thru Paint



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door nsf
Scratched
Over 25mm Not Thru Paint



10: Door nsr
Chipped
Over 5mm



11: Door nsr
Scratched
Over 25mm Not Thru Paint



12: D Post ns
Scratched
Over 25mm Not Thru Paint



13: Door nsr
Chipped
Over 5mm



14: Sill ns
Dented
Over 30mm



15: Wheel nsr
Corroded
Light



16: Wheel osr
Corroded
Light



17: D Post os
Scratched
Over 25mm Not Thru Paint



18: Door osr
Chipped
Over 5mm



19: Door osr
Scratched
Over 25mm Not Thru Paint



20: Door osf
Chipped
Over 5mm



21: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



22: Door osf
Chipped
Over 5mm



23: Wheel osf
Corroded
Light



24: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



25: Wing osf
Scratched
Over 25mm Not Thru Paint



26: Bumper Front
Scratched
Over 25mm Not Thru Paint



27: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK