COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YD23ZGH

Iveco S-Way 490

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Doncaster	**GVW**	44000kg	**Cab Type**	AS SLEEPER CAB
Reg. date	05/06/2023	**Colour**	WHITE	**Gearbox**	AUTOMATIC
Year	2023	**VIN**	ZCFS62NU20C499244	**Axle Combi**	6x2
Mileage	626,086 Km Not Warranted	**Body Style**	Tractor Unit	**Steering Combi**	Mid-Lift
Fuel Type	DIESEL	**MOT Due**	31/10/2027	**Rear Suspension**	Air

SLIDING 5TH WHEEL

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features


- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Navigation system
- Central locking
- Digital radio
- Cloth seat trim

Photos
















16 08 0km/h
626087.0km


D
N
R



IVECO S.p.A.
ZCFS62NU20C499244
26000 kg
11500 kg
AD3C
3
2640 1360
0.516
F3HGE611J 357
SPAIN
IVECO

IVECO












Condition Check




Damage Photos



1: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



2: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



3: Panel Front
Cracked
Replace



4: Panel Front
Chipped
Multiple Chips




5: Panel Front
Missing
Replace



6: Bumper Front Moulding
Broken
Replace



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Qtr Panel Trim ns
Broken
Replace

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK