COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MH23JEO

Iveco Daily 35-140

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	46824
Cap Code	IVDA235S44DDTM2 5 L

Details

Location	Avonmouth	**Colour**	WHITE	**CAP Below**	£10,250.00
Reg. date	25/08/2023	**VIN**	ZCFCL35A10D739788	**Gearbox**	MANUAL
Year	2023	**Body Style**	Dropside	**Gears**	6
Mileage	63,303 Miles Not Warranted	**MOT Due**	24/08/2027	**Tail Lift**	Column
Fuel Type	DIESEL	**CAP Clean**	£12,850.00		
GVW	3500kg	**CAP Average**	£11,900.00		

AD BLUE, E/MIRRORS, 3750 WB

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Auxiliary input socket
- Air conditioning
- Cloth seat trim
- Cruise control
- Digital radio
- Front electric windows
- Navigation system
- Mobile phone App interface
- Drivers airbag
- Park assist camera
- USB/iPod interface
- Central locking

Photos











11°C
Speedometer
0
MPH
12:24




MH23 JEO

IVECO
IVECO SpA
SPAIN
e3*2007/46*0118*
ZCFCL35A10D739788
3500 kg
7000 kg
1- 1900 kg
2- 2240 kg
Type IS35SI2AA
Wheelbase 3750
N° of axles 2
Engine Type F1AGL411B
Engine power kW 100
Corrected absorption value
0.502


PALFINGER
PALFINGER




IVECO
AIR bag

R135
5
6
R 4








Condition Check



Damage Photos



1: Bonnet
Chipped
Over 5mm



2: Wing nsf
Scratched
Over 25mm Not Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Corroded
Light



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Chipped
Over 5mm



8: B Post ns
Chipped
Over 5mm



9: Wheel nsr
Corroded
Light



10: Bumper Rear
Rusted
Over 5mm



11: Wheel osr
Corroded
Light



12: B Post os
Chipped
Over 5mm



13: Door osf
Chipped
Over 5mm



14: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



15: Wheel osf
Corroded
Light



16: Wing osf
Chipped
Over 5mm



17: Bonnet
Chipped
Over 5mm



18: Bumper Front
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK		

Commercial Vehicle Auctions Limited