COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SF23RDO

Fiat Ducato 35 2.2 MUTLIJET 140PS BUSINESS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	57371
Cap Code	FIDU22LBP HDTM2 5 L

Details

Location	Bedford	**GVW**	3500kg	**CAP Clean**	£8,725.00
Reg. date	31/03/2023	**Colour**	WHITE	**CAP Average**	£8,075.00
Year	2023	**VIN**	ZFA25000002W83030	**CAP Below**	£6,950.00
Mileage	69,427 Miles Not Warranted	**Body Style**	Panel Van LWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	30/03/2027	**Gears**	6

WARNING LIGHT ON DASH AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features



- Navigation system
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos










CORSO G. AGNELLI 200
10135 TORINO ITALY
FCA ITALY S.P.A.
ZFA250000*02M83030*
3500 KG KG
6000 KG KG
1- 1870 KG
2- 2000 KG
MOTORE 4H03
VERSIONE 250CBPFC MS
MADE IN ITALY 0.51




Range
1249
69427





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Roof
Dented
Over 30mm



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Door Mirror Assy nsf
Broken
Replace



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel Moulding ns
Missing
Replace



9: Qtr Panel nsr
Dented
With Paint Damage



10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



12: Door nsr
Dented
With Paint Damage



13: Door nsr
Scratched
UpTo 25mm Thru Paint



14: Door osr
Dented
With Paint Damage



15: Qtr Panel osr
Dented
With Paint Damage



16: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



17: Qtr Panel osr
Dented
With Paint Damage



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint




19: Qtr Panel osr
Dented
With Paint Damage



20: Qtr Panel Moulding os
Missing
Replace



21: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



22: Qtr Panel osr
Dented
Between 10mm + 30mm



23: Door osf
Scratched
Over 25mm Not Thru Paint



24: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault