COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MF23CKD

Iveco Daily 35-140

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	46824
Cap Code	IVDA235S44DDTM2 5 L

Details

Location	Avonmouth	**Colour**	WHITE	**CAP Below**	£10,800.00
Reg. date	25/08/2023	**VIN**	ZCFCL35A00D739667	**Gearbox**	MANUAL
Year	2023	**Body Style**	Dropside	**Gears**	6
Mileage	53,220 Miles Not Warranted	**MOT Due**	24/08/2027	**Tail Lift**	Column
Fuel Type	DIESEL	**CAP Clean**	£13,550.00		
GVW	3500kg	**CAP Average**	£12,550.00		

WARNING LIGHT ON DASH, AD BLUE, TOW BAR, E/MIRRORS, 3750 WB

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Auxiliary input socket
- Air conditioning
- Cloth seat trim
- Cruise control
- Digital radio
- Front electric windows
- Navigation system
- Mobile phone App interface
- Drivers airbag
- Park assist camera
- USB/iPod interface
- Central locking

Photos













MPH





IVECO SpA
ZCFCL35A00D739667
3500 kg
7000 kg
1 - 1900 kg
2 - 2240 kg
Type 1535S12AA
Wheelbase 3750
Engine Type F1AGL411B
100


PALFINGER
PALFINGER



IVECO



CAM1
MENU
MODE







Condition Check



Damage Photos



1: Bonnet
Chipped
Over 5mm



2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



6: B Post ns
Chipped
Over 5mm



7: B Post ns
Dented
Over 30mm



8: Wheel nsf
Corroded
Light



9: Wheel nsr
Corroded
Light



10: Bumper Rear
Rusted
Over 5mm



11: Wheel osr
Corroded
Light



12: B Post os
Chipped
Over 5mm



13: Door osf
Chipped
Over 5mm



14: Door osf
Scratched
Over 25mm Thru Paint



15: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



16: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



17: Wheel osf
Corroded
Light



18: Bumper Front
Scratched
Over 25mm Not Thru Paint



19: Switches And Controls
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK		