COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**PE65UZR**

## Daf LF 220

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Plus VAT |
| **V5** | Present |
| **Cap Code** | 999900 |

### Details

| | |
|---|---|
| **Location** | Doncaster |
| **Reg. date** | 04/11/2015 |
| **Year** | 2015 |
| **Mileage** | 830,707 Km Warranted |
| **Fuel Type** | DIESEL |
| **GVW** | 18000kg |
| **Colour** | RED |

| | |
|---|---|
| **VIN** | XLRAEL3700L448331 |
| **Body Style** | Box Van |
| **Service history** | Yes |
| **Service documents** | Printout |
| **Number of stamps** | 11 |
| **Last service date** | 30/07/2025 |
| **Last service miles** | 733,726 |

| | |
|---|---|
| **MOT Due** | 31/03/2027 |
| **Cab Type** | DAY CAB |
| **Gearbox** | AUTOMATIC |
| **Axle Combi** | 4x2 |
| **Rear Suspension** | Steel |
| **Rear Doors** | Roller |
| **Tail Lift** | Cantilever |

*COLLECTED AS NON-RUNNER - ENGINE ISSUES, TAIL LIFT INOP*

### Tyres

| | | | | |
|---|---|---|---|---|
| **NSF** | **NSI1** | **NSI2** | **NSI3** | **NSI4** |
| **OSF** | **OSI1** | **OSI2** | **OSI3** | **OSI4** |
| **Spare** | **NSO1** | **NSO2** | **NSO3** | **NSO4** |
| | **OSO1** | **OSO2** | **OSO3** | **OSO4** |

## Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Digital radio
- Central locking
- Radio/CD
- Cloth seat trim

## Photos















0km/h
707.9km
OK
2

R
N
D

Plate
DAF ILF 220 FA
RIGID R
DEPARTMENT FOR TRANSPORT GREAT BRITAIN
REPLACEMENT

DAF TRUCKS N.V.
XLRAEL3700L448331
GB
DAF



s when studs changed)
CHASSIS No.:
BUILD DATE:
DAF



PE65 UZR







# Condition Check




## Damage Photos




1: Panel Front
Chipped
Multiple Chips




2: Other
N/A
N/A



3: Qtr Panel osr
Scratched
Over 25mm Thru Paint



4: Door osf
Scratched
Over 25mm Thru Paint



5: Door osf
Dented
With Paint Damage



6: Door Pad osf
Soiled
Heavy

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | OK | **Upholstery Condition** | Poor |
| **Seat Condition** | OK | **Odour** | - |

| | | | |
|---|---|---|---|
| Engine Runs | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| ABS light illuminated | OK | DPF light illuminated | OK |
| | | Service indicator light illuminated | OK |