COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BU20OKC

DAF LF 230

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Doncaster	**Colour**	WHITE	**Axle Combi**	4x2
Reg. date	03/03/2020	**VIN**	XLRAEL3700L491695	**Rear Suspension**	Air
Year	2020	**Body Style**	Fridge Box	**Rear Doors**	Roller
Mileage	449,732 Km Not Warranted	**MOT Due**	31/03/2027	**Tail Lift**	Tuckaway
Fuel Type	DIESEL	**Cab Type**	DAY CAB		
GVW	18000kg	**Gearbox**	AUTOMATIC		

THERMOKING T-1000R UNIT, STANDBY PLUG

Tyres


NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features


- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Radio/CD
- Cloth seat trim
- Park assist camera
- Air conditioning
- Auxiliary input socket
- Front electric windows

Photos










17 15
0km/h
449732.8km


DVS


DAF TRUCKS N.V.
DAF








BU20 OKC








Condition Check



Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



3: Tailgate
Hole
Over 10mm



4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Door osf
Scratched
Over 25mm Thru Paint



6: Door Pad osf
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	Poor
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK