COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE67HTZ

Volvo FMX 410

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Doncaster	**GVW**	32000kg	**MOT Due**	31/03/2027
Reg. date	24/10/2017	**Colour**	WHITE	**Cab Type**	DAY CAB
Year	2017	**VIN**	YV2XZ22G0HB829876	**Gearbox**	AUTOMATIC
Mileage	411,463 Km Not Warranted	**Body Style**	Tipper	**Axle Combi**	8x4
Fuel Type	DIESEL	**Service history**	None	**Rear Suspension**	Steel

WARNING LIGHT ON DASH EDBRO TIPPING GEAR, WEIGH SYSTEM

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**


Features


- Bluetooth connection
- Front electric windows
- Cruise control
- Drivers airbag
- Digital radio
- Central locking
- Air conditioning
- Leather seat trim

Photos













16:36 0km/h
OUT 411464.0km
OK






Volvo Truck Corporation
Drive
WB
Product type
Vehicle type


PE67 HTZ
VOLVO


PE67 HTZ
VOLVO






MAX
MIN
MAX PRESSURE
SERIAL NUMBER
Edbro


PE67 HTZ





















Condition Check



Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Door osf
Chipped
Multiple Chips



3: Door nsf
Dented
With Paint Damage



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Dented
With Paint Damage

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK