COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YD73ZBZ

Iveco S-Way 490

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Photocopy
Cap Code	999900

Details

Location	Doncaster	**GVW**	44000kg	**Gearbox**	AUTOMATIC
Reg. date	09/10/2023	**Colour**	WHITE	**Axle Combi**	6x2
Year	2023	**VIN**	ZCFS62NU70C499725	**Steering Combi**	Mid-Lift
Mileage	381,134 Km Warranted	**Body Style**	Tractor Unit	**Rear Suspension**	Air
Fuel Type	DIESEL	**Cab Type**	AS SLEEPER		

SLIDING 5TH WHEEL

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Cloth seat trim
- Digital radio
- Air conditioning


Photos













10:45
0km/h
381134.2km
OK
YD73ZBZ



D
N
R

IVECO S.p.A.
IVECO




IVECO


IVECO






Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Panel Front
Missing
Replace



3: Panel Front
Missing
Replace



4: Bumper Front
Dented
With Paint Damage



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Fascia Panel
Broken
Replace

Interior

Carpet Condition	OK	**Upholstery Condition**	Poor
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK