COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PF65UGY

Daf LF 250

Non Runner

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Bedford	**GVW**	18000kg	**Cab Type**	DAY CAB
Reg. date	01/01/2016	**Colour**	WHITE	**Gearbox**	AUTOMATIC
Year	2016	**VIN**	XLRAEL3700L447978	**Axle Combi**	4x2
Mileage	Not Showing	**Body Style**	Dropside	**Rear Suspension**	Steel
Fuel Type	DIESEL	**MOT Due**	31/05/2027		



NON RUNNER-NO KEYS, VEHICLE LOCKED MOT SHOWS 433,433KM 20/05/2026

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Photos






DAF
PF65 UGY

PF65 UGY






Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Wing osf
Scratched
UpTo 25mm Thru Paint



3: Screen Front
Cracked
Replace



4: Bonnet
Chipped
Multiple Chips



5: Bonnet
Scratched
UpTo 25mm Thru Paint



6: Wing nsf
Cracked
Replace



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Wing Front Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



12: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-