COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YD73ZHF

Iveco S-Way 490

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Photocopy
Cap Code	999900

Details

Location	Doncaster	**GVW**	44000kg	**Cab Type**	AS SLEEPER CAB
Reg. date	09/10/2023	**Colour**	WHITE	**Gearbox**	AUTOMATIC
Year	2023	**VIN**	ZCFS62NU80C502678	**Axle Combi**	6x2
Mileage	380,010 Km Not Warranted	**Body Style**	Tractor Unit	**Steering Combi**	Mid-Lift
Fuel Type	DIESEL	**Service history**	None	**Rear Suspension**	Air

SLIDING 5TH WHEEL

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features


- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Navigation system
- Central locking
- Digital radio
- Cloth seat trim

Photos
















09:42
0km/h
380010.9km
OK

D
N
R


IVECO S.p.A.
ZCFS62NUB0C5026?8
11500
AD3C
3
2640 1360
0.516
F3HGE611J 357
SPAIN
IVECO





IVECO








Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm



2: Panel Front
Missing
Replace



3: Bumper Front
Cracked
Over 25mm



4: Panel Front
Missing
Replace

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK