COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LK17WVW

Isuzu N75.150

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**GVW**	4460kg	**Cab Type**	DAY CAB
Reg. date	09/03/2017	**Colour**	WHITE	**Gearbox**	AUTOMATIC
Year	2017	**VIN**	JAANPR85MF7100075	**Axle Combi**	4x2
Mileage	367,785 Km Not Warranted	**Body Style**	Tilt & Slide	**Rear Suspension**	Steel
Fuel Type	DIESEL	**MOT Due**	31/05/2027		

SPEC LIFT, WNCH

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features


- Bluetooth connection
- Drivers airbag
- Digital radio
- Passenger airbag
- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim

Photos










VDO
17:00
367785.6KM



ECO
P
N
D
L
+
M




ISUZU MOTORS LTD.
e4*2007/46*0324
GVW 7500 Kg
GCW 11000 Kg
AXLE 1 3100 Kg
AXLE 2 6000 Kg
P.NO.8981893111


ISUZU
LK17 MVW


ISUZU
LK17 MVW

























Condition Check



Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Door nsf
Dented
With Paint Damage



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Door osf
Dented
With Paint Damage



5: Door Mirror Assy osf
Broken
Replace



6: Door Mirror Assy nsf
Broken
Replace



7: Seat Base Cover osf
Holed
Over 3mm



8: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK