COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

GD17VJU

Daf LF 210

Inspection

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**GVW**	12000kg	**MOT Due**	31/12/2026
Reg. date	28/07/2017	**Colour**	WHITE	**Cab Type**	DAY CAB
Year	2017	**VIN**	XLRAEL1500L464965	**Gearbox**	AUTOMATIC
Mileage	416,370 Km Not Warranted	**Body Style**	Car Transporter	**Axle Combi**	4x2
Fuel Type	DIESEL	**Service history**	None	**Rear Suspension**	Air

JJ CONVERSIONS BODY, WINCH


Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim

Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Panel Front
Chipped
Multiple Chips



4: Number Plate Front
Broken
Replace



5: Bumper Front
Dented
With Paint Damage



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Door osf
Chipped
Multiple Chips



9: Door Pad osf
Soiled
Heavy



10: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	**Upholstery Condition**	Poor
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK