COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SN26TNO

LAND ROVER DEFENDER 90 3.0 D250 X-Dynamic SE

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Buyer To Apply
Cap Id	107653
Cap Code	LRDE30XE63EDTA4 1

Details

Location	Livingston	**Colour**	BLACK	**CAP Below**	£44,400.00
Reg. date	07/07/2026	**VIN**	SALEA6AW3T2623591	**Gearbox**	AUTOMATIC
Year	2026	**Body Style**	Estate	**Gears**	8
Mileage	6,929 Miles Not Warranted	**MOT Due**	06/07/2029	**Doors**	3
Fuel Type	DIESEL	**CAP Clean**	£47,800.00	**Axle Combi**	4x4
GVW	3050kg	**CAP Average**	£46,100.00		

SLIDING PANOARMIC ROOF, TOWING PACK, AIR SUSPENSION PACK, COLD CLIMATE PACK, FIXED SIDE STEPS, PRIVACY GLASS, KEYLESS IGNITION, LEATHER, REAR VIEW CAMERA.

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Front parking sensor
- Radio/CD
- Climate control
- Heated front seat
- Body coloured bumpers
- Front electric windows
- Navigation system
- Electric door mirrors
- Alloy wheels
- Rear parking sensor
- Air conditioning
- Spare wheel

Photos











Trip Auto summary
Clyde 1
Clyde 1 -- The Biggest Hits The Big...


GHR 70s
GHR 80s
GO Radio
Gold UK
Grt Hits
Heart UK
Heart80s
Heart70s
PLAYER
FAVOURITES
STATIONS





SN26 TNO


JAGUAR LAND ROVER LTD
SALEA6AW3T2623591
3050 kg
6550 kg
PRIMARY COLOUR REFERENCE
1AG - SANTORINI BLACK














Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK

Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK