COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PO21YVZ

Mercedes-Benz Sprinter 314 CDI Progressive

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	49662
Cap Code	MESP2133PGDDTM2 5 L

Details

Location	Livingston	**Colour**	WHITE	**CAP Below**	£4,200.00
Reg. date	12/03/2021	**VIN**	W1V9071352N119359	**Gearbox**	MANUAL
Year	2021	**Body Style**	Dropside L3	**Gears**	6
Mileage	231,295 Miles Warranted	**MOT Due**	26/03/2027	**Tail Lift**	Column
Fuel Type	DIESEL	**CAP Clean**	£5,775.00		
GVW	3500kg	**CAP Average**	£5,100.00		

WARNING LIGHTS ON DASH TOW BAR, REAR VIEW CAMERA.

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Front electric windows
- Central locking

Photos







13:36
0km/h
OUT 372246.3km



MERCEDES-BENZ AG
e1*2007/46*0300
W1V9071352N119359
Mercedes-Benz
3500 kg
7000 kg
1650 kg
2250 kg
Typ: 906BA35
Made in Germany






13:42

Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Wing nsf
Chipped
Multiple Chips



3: Bonnet
Dented
With Paint Damage



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wing osf
Dented
With Paint Damage



6: Door osf
Scratched
Over 25mm Thru Paint



7: Door osf
Dented
Over 30mm



8: Roof
Dented
Over 30mm



9: Tailgate
Chipped
Multiple Chips



10: Door nsf
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK