COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YJ19YML

Fiat Doblo 1.6 Multijet 16V

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	34212
Cap Code	FIDO16MAXSVDTM2 4 L

Details

Location	Doncaster
Reg. date	21/03/2019
Year	2019
Mileage	110,923 Miles Warranted
Fuel Type	DIESEL
GVW	2465kg
Colour	WHITE

VIN	ZFA26300006M82693
Body Style	Panel Van L2
Service history	Yes
Service documents	Service Book
Number of stamps	8
Last service date	29/04/2026
Last service miles	108,193

MOT Due	20/03/2027
CAP Clean	£2,850.00
CAP Average	£2,475.00
CAP Below	£1,925.00
Gearbox	MANUAL
Gears	5

TWIN SIDE LOAD DOORS, E/MIRRORS, AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Front electric windows
- Rear parking sensor
- Drivers airbag
- Digital radio
- Central locking
- Air conditioning
- Cloth seat trim

Photos





























Commercial Vehicle Auctions Limited







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Scratched
Over 25mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



4: Qtr Panel nsr
Dented
Over 30mm



5: Qtr Panel nsr
Dented
With Paint Damage



6: Door nsr
Dented
With Paint Damage



7: Qtr Panel osr
Dented
Over 30% Of Panel



8: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	Yes

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK