COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CE20XLN

Citroen Dispatch 1400 2.0 BlueHDi 120PS Enterprise

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	39362
Cap Code	CIDI20342EVDTM2 4 L

Details

Location	Doncaster
Reg. date	01/04/2020
Year	2020
Mileage	149,186 Miles Warranted
Fuel Type	DIESEL
GVW	3100kg
Colour	WHITE

VIN	VF7VFAHKKL7024850
Body Style	Panel Van LWB
Service history	Yes
Service documents	Service Book
Number of stamps	7
Last service date	14/04/2026
Last service miles	132,641

MOT Due	15/04/2027
CAP Clean	£3,750.00
CAP Average	£3,300.00
CAP Below	£2,650.00
Gearbox	MANUAL
Gears	6

OUTSTANDING RECALL TWIN SIDE LOAD DOORS, E/MIRRORS, AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos









18 MI
149 186 MI


AUTOMOBILES CITROEN
VF7VFAHKKL7024850
3100 KG
5000 KG
1- 1500 KG
2- 1800 KG
VFAHKK-B2F01E













Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Door nsf
Chipped
Over 5mm



3: Door nsr
Scratched
Over 25mm Thru Paint



4: Door osr
Scratched
Over 25mm Thru Paint



5: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



6: Qtr Panel osr
Chipped
Multiple Chips



7: Door osf
Chipped
Multiple Chips



8: Screen Front
Cracked
Replace

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK