

# VEHICLE INSPECTION REPORT

**C506624**

## CARTWRIGHT CURTAINSIDE

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | N/A      |

### Details

|           |            |            |                   |                 |      |
|-----------|------------|------------|-------------------|-----------------|------|
| Reg. date | 01/01/2019 | Colour     | BLUE              | Brakes          | Drum |
| Year      | 2019       | VIN        | SMWCS39SFKA191428 | Axle Combi      | Tri  |
| Mileage   | TBC        | Body Style | Trailer           | Rear Suspension | Air  |
| Fuel Type |            | MOT Due    | 30/06/2025        | Rear Doors      | Barn |

BPW AXLES, FERRY LASHING RINGS, ENXL RATED CURTAINS

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos





