

VEHICLE INSPECTION REPORT

CK71RCO

Ford Transit 350 2.0 ECOBLUE 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 18/02/2022

Year 2022

Mileage 83,364 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0EXXTTREM44033

Body Style Panel Van L2

MOT Due 26/09/2025

CAP Clean £9,150.00

CAP Average £8,475.00

CAP Below £7,325.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Digital radio
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel nsr
Dented
Over 30mm

No Image



4:

3: Qtr Panel nsr
Hole
Over 10mm



5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: C Post ns
Scratched
Over 25mm Thru Paint



8: Door nsr
Dented
Over 30mm



9: Door nsr
Dented
Over 30mm



10: Door osr
Dented
With Paint Damage



11: C Post os
Scratched
Over 25mm Thru Paint




12: Qtr Panel osr
Dented
Over 30mm



13: Screen Front
Chipped
UpTo 10mm



14: Seat Base Cover nsf
Soiled
Heavy



15: Seat Base Cover osf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		