COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR23XCK

Maxus Deliver 9 2.0 D20 150PS

Non Runner

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	MXD920L150HDTM2 L

Details

Location	Doncaster	**Fuel Type**	DIESEL	**Body Style**	Fridge Van LWB
Reg. date	15/06/2023	**GVW**	3500kg	**Gearbox**	MANUAL
Year	2023	**Colour**	WHITE	**Gears**	6
Mileage	63,699 Miles Not Warranted	**VIN**	LSH14J7C6PA085882		

WARNING LIGHTS ON DASH AD-BLUE, THERMO KING UNIT, SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag

Photos










63699mi


SAIC MAXUS Autdmotive Co.,Ltd.
LSH14J7C6PA085882
3500 kg
6000 kg
1. 1950 kg
2. 1900 kg







AIRBAG







Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm



2: Bonnet
Chipped
Multiple Chips



3: Number Plate Front
Broken
Replace



4: Bumper Front
Cracked
Over 25mm



5: Bumper Front
Scratched
25 to 100mm Thru Paint



6: Door Mirror Assy nsf
Broken
Replace



7: Door nsf
Dented
Over 30mm



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
Over 30mm



12: Qtr Panel nsr
Dented
With Paint Damage



13: Door nsr
Dented
Over 30mm



14: Lamp nsr
Broken
Replace



15: Door nsr
Dented
With Paint Damage



16: Door osr
Dented
With Paint Damage



17: Door osr
Dented
With Paint Damage



18: Qtr Panel osr
Dented
With Paint Damage



19: Qtr Panel osr
Dented
With Paint Damage



20: Qtr Panel osr
Dented
Over 30mm



21: Door osf
Dented
With Paint Damage



22: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



23: Carpets Front
Holed
Over 3mm



24: Door Pad osf
Soiled
Heavy



25: Seat Base Cover nsf
Soiled
Heavy



26: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	**Upholstery Condition**	Poor
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault