

VEHICLE INSPECTION REPORT

PN66PXM

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	07/11/2016	Colour	WHITE/GREEN	Cab Type	DAY CAB
Year	2016	VIN	XLRACM4100G104692	Gearbox	AUTOMATIC
Mileage	303,975 Km Warranted	Body Style	Flatbed & Crane	Axle Combi	8x2
Fuel Type	Diesel	MOT Due	31/12/2025	Rear Suspension	Air

PALFINGER PK78002 REMOTE CRANE (YEAR 2016), WREIGH SYSTEM, TWIST LOCKS (6)

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Cracked
Replace



4: Bumper Front
Dented
With Paint Damage



5: Panel Front
Scratched
Over 25mm Not Thru Paint



6: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		