

# VEHICLE INSPECTION REPORT

**C355313**

## DON-BUR BOX

### Inspection

### Vehicle

VAT	Plus VAT
V5	N/A

### Details

Reg. date	01/01/2013	VIN	SEPBV38GKDL061812	Axle Combi	Tri
Year	2013	Body Style	Trailer	Rear Suspension	Air
Mileage	TBC	Service history	Yes	Rear Doors	Roller
Fuel Type		MOT Due	Expired		
Colour	RED	Brakes	Disc		

\*MECHANICAL W/O\* 13.6M, 4.24M, BPW AXLES, FRONT LIFT AXLE, RAISE & LOWER VALVE, FERRY LASHING RINGS

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos







