

VEHICLE INSPECTION REPORT

C356003

DON-BUR BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	VIN	SEPBV38GKDL061868	Brakes	Disc
Year	2013	Body Style	Trailer	Axle Combi	Tri
Mileage	TBC	Service history	Yes	Rear Suspension	Air
Fuel Type		Service documents	Printout	Rear Doors	Roller
Colour		MOT Due	Expired		

CORROSION 13.6M, 4.24M, BPW AXLES, FRONT LIFT AXLE, RAISE & LOWER VALVE, FERRY LASHING RING

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



